

MAXNET II° - MP3BAS - Ultra-dense Active Chassis Only FIRMWARE UPDATE NOTICE

Version:

mn2s.1.6.37

Issued:

June 26, 2014

Fixes:

- ▶ Slot 9 disappearing when Slot 8 & 9 had MPSA8x2 or MPSABCNC modules installed.
- ▶ Log timing stamp issue.
- ▶ NTC time server not working.

Known Issues:

- Latest versions of Internet Explorer® will not display graphics correctly. It is a display issue only. No function loss.
- ▶ LED status can take up to 1 minute to display state change.
- ▶ Re-seating module MPSA8x2 or MPSABCNC before GUI clear causes LED to default to no alarm even if an alarm is present.



Service & Support

Contact ATX Networks

Please contact ATX Technical Support for assistance with any ATX products. Please contact ATX Customer Service to obtain a valid RMA number for any ATX products that require service and are in or out-of-warranty before returning a failed module to the factory.

TECHNICAL SUPPORT

Tel: 289.204.7800 – press 1

Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only

Email: <u>support@atx.com</u>

SALES ASSISTANCE

Tel: 289.204.7800 – press 2

Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only

Email: <u>insidesales@atx.com</u>

FOR ASSISTANCE WITH AN EXISTING ORDER

Tel: 289.204.7800 – press 3

Toll-Free: 866.YOUR.ATX (866.968.7289) USA & Canada only

Email: <u>orders@atx.com</u>
Web: <u>www.atx.com</u>

Although every effort has been taken to ensure the accuracy of this document it may be necessary, without notice, to make amendments or correct omissions.

MAXNET® II is a registered trademark of ATX in the United States and/or other countries. Products or features contained herein may be covered by one or more U.S. or foreign patents. Other non-ATX product and company names in this manual are the property of their respective companies.

© 2019 by ATX Networks Corp. and its affiliates (collectively "ATX Networks Corp."). All rights reserved. This material may not be published, broadcast, rewritten, or redistributed. Information in this document is subject to change without notice.



8-1602 Tricont Avenue, Whitby, ON L1N 7C3 Canada Tel: 289.204.7800 | Toll-Free: 866.YOUR.ATX (866.968.7289) www.atx.com support@atx.com